

I. Stroke 1. Isothermal Expansion.

$$q_2 = -w_1 = RT_2 \ln (V_2/V_1)$$
 ...(1)

## II. Stroke 2. Adiabatic Expansion.

Now, by definition, 
$$C_{\mathbf{v}} = (\partial U/\partial T)_{\mathbf{v}}$$
 ...(2)  

$$\Delta U = C_{\mathbf{v}} \Delta T = C_{\mathbf{v}} (T_1 - T_2) = -w$$
 ...(3)  
(change in temperature,  $\Delta T$  = final temperature - initial temperature)  
or  $-w = C_{\mathbf{v}} (T_1 - T_2) = -C_{\mathbf{v}} (T_2 - T_1)$  ...(4)  
If the work done in this stage is denoted by  $w_2$ , then  

$$w_2 = -C_{\mathbf{v}} (T_2 - T_1)$$
 ...(5)

III. Stroke 3. Isothermal Compression.

$$-q_1 = w_3 = RT_1 \ln (V_4/V_3)$$
 ...(6)

## IV. Stroke 4. Adiabatic Compression.

$$\Delta U = w = C_{\nu} \Delta T = C_{\nu} (T_2 - T_1).$$

Let w<sub>4</sub> be the work done in this stage. Then,

$$w_4 = C_\nu (T_2 - T_1)$$

The net heat absorbed (q) by the ideal gas in the whole cycle is given by

$$q = q_2 + (-q_1) = RT_2 \ln (V_2/V_1) + RT_1 \ln (V_4/V_3)$$
  
=  $RT_2 \ln (V_2/V_1) - RT_1 \ln (V_3/V_4)$ 

$$C_{\nu} \ln (T_2/T_1) = R \ln (V_3/V_2)$$
 (For stage II)  
 $C_{\nu} \ln (T_2/T_1) = R \ln (V_4/V_1)$  (For stage IV)  
 $V_3/V_2 = V_4/V_1$  or  $V_2/V_1 = V_3/V_4$ 

$$q = q_2 - q_1 = R (T_2 - T_1) \ln (V_2/V_1)$$

Similarly, the net work done by the gas is given by

$$w = -w_1 + (-w_2) + w_3 + w_4$$

$$= RT_2 \ln V_2/V_1 - C_v(T_2 - T_1) + RT_1 \ln (V_4/V_3) + C_v(T_2 - T_1)$$

$$= RT_2 \ln (V_2/V_1) - RT_1 \ln (V_3/V_4)$$

Since

$$V_2/V_1 = V_3/V_4$$

Hence, •

300

$$w = R(T_2 - T_1) \ln (V_2/V_1)$$

$$q_2 = RT_2 \ln (V_2/V_1)$$

12 by Eq. 1,

$$w = q_2 (T_2 - T_1)/T_2$$

Efficiency of a Heat Engine. The fraction of the heat absorbed by an engine which it can convert into work gives the efficiency  $(\eta)$  of the engine.

From Eq. 13, it is seen that

Efficiency, 
$$\eta = w/q_2 = (T_2 - T_1)/T_2$$
 ....(14)